Dell Precision 7510 Hard Drive Replacement

Written By: Johnathan Hammond

This document was generated on 2022-11-19 02:10:04 AM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 1 of 4

TOOLS:

- Phillips #0 Screwdriver (1)

PARTS:

- Crucial MX500 1 TB SSD (1)
- Crucial MX500 250 GB SSD (1)
- Crucial MX500 500 GB SSD (1)
- Crucial MX500 2 TB SSD (1)

This document was generated on 2022-11-19 02:10:04 AM (MST).

Step 1 — Removing the Battery Cover

- Slide the release latch to unlock the battery cover.

- Slide and lift the battery cover to remove it from the computer.

## Step 2 — Removing the Battery Cover

- Slide the release latch to unlock the battery cover.

- Slide and lift the battery cover to remove it from the computer.

This document was generated on 2022-11-19 02:10:04 AM (MST).

Step 3 — Removing the Hard Drive

- Remove the screws that secure the hard drive to the computer.

- Lift the hard-drive latch to the unlock position.

- Slide and lift the hard drive from the computer.

Step 4 — Remove the Screws

- Remove the screws that secure the hard drive. Lift the hard drive away from the bracket.

This document was generated on 2022-11-19 02:10:04 AM (MST).