




Fahrenheit FHT 125PRMR Power Cord Replacement

Replacing the power cord of your Fahrenheit FHT 125PRMR.

Written By: Joshua Potts



INTRODUCTION

Is the device not turning on when plug in? This guide will help you replace the power cord to fix the issue.



TOOLS:

- [iFixit Opening Tools](#) (1)
 - [Phillips #2 Screwdriver](#) (1)
 - [Phillips #1 Screwdriver](#) (1)
-

Step 1 — Power Cord



- Use your fingers or a plastic opening tool to open the side hinges on both sides of the device.

Step 2



- Using a Philips head #2 screwdriver remove the 7mm black screw from the hinge of the device.

Step 3



- Using the metal spudger, push through the hole the screw was removed from. Doing this will push the copper pin out of the other side.
- When the pin is removed the two sides of the device can now separate.
- ⓘ Be sure to collect the spring that is next to the hinge when they are separated.

Step 4



- Use the Phillips Head 1 screwdriver to remove the two screws on the back where the power cable exits the device.
- Once the two screws are removed; simply lift the case up and off to have access to the power cable.

Step 5



- To remove the power cable, grab the clear plastic holding and the base of the power cable and pull apart.

To reassemble your device, follow these instructions in reverse order.