

iMac Intel 20" EMC 2105 and 2118 Access Door Replacement

Written By: Walter Galan



This document was generated on 2020-11-24 10:52:11 PM (MST).

INTRODUCTION


Remove the access door to replace RAM chips.

FTOOLS:

• Phillips #1 Screwdriver (1)

This document was generated on 2020-11-24 10:52:11 PM (MST).

Step 1 — Access Door



- Loosen the two Phillips screws securing the access door to your iMac.
- (i) Both screws remain captive within the access door.
- Remove the access door.

A Before beginning the repair, unplug the computer and press and hold the power switch for 20-30 seconds, to discharge internal capacitors.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-24 10:52:11 PM (MST).