



Smartab STJR700 Screen/Digitizer Replacement

Written By: Tianna Edwards



TOOLS:

Flathead 3/32" or 2.5 mm Screwdriver (1)
iFixit Opening Tool (1)

Step 1 — Screen/Digitizer



- There are four screws with each one in each corner. Use the screwdriver to unscrew the back or bottom of the device.

Step 2



- Remove the bottom or back of the device by detaching the black bottom after removing the screws.
- the front panel should now be exposing the digitizer along with the other electronic components of the device.

Step 3



- Next, remove the circuit board from the front panel and screen. This should leave the digitizer and circuit board intact.
- Afterward, remove the existing damaged glass part of the device from the front panel as shown in the last picture.
- Finally add a new STJR700 screen and reverse the previous steps to reattach the device.

To reassemble your device, follow these instructions in reverse order.