

# Garmin Nuvi 1490T Front Frame Panel Replacement

Replace damaged frame to have your GPS look new again.

Written By: Ricardo Solis



This document was generated on 2020-11-17 08:22:05 AM (MST).

### **INTRODUCTION**

This repair is easy and quick to fix and only requires a plastic prying tool to get the job done. This repair will have your GPS looking new again.



## **TOOLS:**

• iFixit Opening Tools (1)

#### **Step 1 — Front Frame Panel**



- Power off your GPS before moving on.
- Locate the crevice that separates the frame from the body.

#### Step 2



- Carefully insert the plastic prying tool into the crevice to separate the frame from the body.
- Applying excessive force can lead to a damaged or scratched display screen.

## Step 3





Slide the plastic prying tool around the perimeter to completely remove the frame.

To reassemble your device, follow these instructions in reverse order.